Transducer bracket mounting

Use the stainless steel plate screws that come with the bracket to mount the bracket to the stern transom. You will need a ∅ 3,5 mm drill to get the job done.

To seal off the screws, use a sealant, e.g. Sikaflex Sealant.



When mounting the transducer bracket, make sure that the transducer sensor is not straight on the line of the lifting strake. This causes a swirl, which then might give the sensor wrong information.

Silver®